LOCAL NOTICE TO MARINERS

APRIL WEEKLY SUPPLEMENT

NOTICE NUMBER 17-97

April 22, 1997

Issued by: Commander, Seventh Coast Guard District (oan)

Brickell Plaza, Federal Building 909 S.E. 1st Avenue, Miami, Florida 33131-3050 Telephone (305) 536-5621 (Office hours 7:30 a.m. - 4:00 p.m., M-F)

BROADCAST NOTICE TO MARINERS

Navigation information having been of immediate concern to the Mariner, and promulgated by the following broadcasts, has been incorporated in this notice when still effective:

- CCGD7 (D7) BNM 425-97 TO 448-97
- GROUP CHARLESTON (CHA) BNM 159-97 TO 174-97
- GROUP MAYPORT (MAY) BNM 230-97 TO 245-97
- GROUP MIAMI (MIA) BNM 204-97 TO 217-97
- GROUP KEY WEST (KEY) BNM 055-97 TO 057-97
- GROUP ST. PETERSBURG (STP) BNM 249-97 TO 267-97
- SAN JUAN (SJ) BNM 143-97 TO 154-97

NOTES: (1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution.

(2) A dark vertical line in the left margin indicates new information.

(3) The Local Notice to Mariners consists of a Monthly Edition and Weekly Supplementals. The Monthly Edition should be maintained as a reference. Recurring information is published only once a month.

REFERENCES: Light List, Vol. III, Atlantic and Gulf Coasts, 1996 Edition (COMDTPUB P16502.3).

U.S. Coast Pilot 4, Atlantic Coast: Cape Henry to Key West (31st Edition).

U.S. Coast Pilot 5, Atlantic Coast: Gulf of Mexico, Puerto Rico, and Virgin Islands (26 th Edition).

* * * * * * * * *

REPORT DISCREPANCIES IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

* * * * * * * * *

I. SPECIAL NOTICE

EXCERPT FROM FEDERAL REGISTER ARTICLE -

Radar-Observer Endorsement for Operators of Uninspected Towing Vessels

The following information is an excerpt of Federal Register, Vol. 62, No. 47, Tuesday, March 11, 1997, Pages 11298 - 11305.

Agency: Coast Guard, DOT. Action: Final rule.

Summary: The Coast Guard amends its rules to require a Radar-Observer endorsement. This final rule requires radar training for licensed masters, mates, and operators of radar-equipped uninspected towing vessels 8 meters (approximately 26 feet) or more in length, toward the endorsement. The rule is necessary to ensure that radar-equipped towing vessels are manned by mariners with the qualifications, skills, and knowledge to operate the radar equipment on board.

Dates: This final rule is effective on March 11, 1997.

Addresses: Unless otherwise indicated, documents referred to in this preamble are available for inspection or copying at the office of the Executive Secretary, Marine Safety Council (G-LRA, 3406), U.S. Coast Guard Headquarters, 2100 Second Street SW., room 3406, Washington, DC 20593-0001 between 9:30 a.m. and 2 p.m., Monday through Friday, except Federal holidays. The telephone number is (202) 267-1477.

For Further Information Contact: Lieutenant Commander Donald J. Darcy, Project Manager, Division of Maritime Personnel Qualifications (G-MSO-1), telephone (202) 267-0221, between 7 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

SAFE BOATING AND SEAMANSHIP COURSES

HOST DATES TIME LOCATION

U.S. Coast Guard Au	xiliary Starting Apr 29, 1	1997 7:30 p.m	9:30 p.m.	Deerfield Bch
Fire Station				
Flotilla 3-10 (Boa	ting Skills & Seamanship) (Tuesdays)	2 nd floor, H	illsboro & Fed Hwy
(561) 392-6230	Deerfield	l Bch, FL		

U.S. Coast Guard Auxiliary Starting May 06, 1997 Staring 7:30 p.m. Flotilla 81 Training Center

Flotilla 81 (Boating Skills & Seamanship) (Tuesdays and Thursdays) 4208 129 St. 722-6971, 778-5800, or 798-9544 (3 weeks) Cortez, FL

U.S. Coast Guard Auxiliary Starting May 05, 1997 7:00 p.m. - 9:00 p.m. Gulf High School

Division 11 (Power Boating Skills) (Tuesdays and Thursdays) New Port Richey, FL Leon Scicchitano (813) 842-9482

U.S. Coast Guard Auxiliary Starting May 05, 1997 7:00 p.m. - 9:00 p.m. Tarpon Springs High School

Division 11 (Power Boating Skills) (Mondays and Thursdays) 1141 Gulf Rd Carl Heinisch (813) 737-2861 Tarpon Springs, FL

Courses are free; however, there is a small fee for text, workbooks, etc.

II. NEW DISCREPANCIES-DISCREPANCIES CORRECTED

The following is a partial list of aids that were not watching as advertised in the Light List as of 1:00 a.m. on the date of this Notice and a list of aids previously reported discrepant that have been corrected since the last Local Notice to Mariners. Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution. For a complete list of discrepancies and for descriptions of abbreviations see Monthly Local Notice to Mariners 13-97.

FEDERAL AID DISCREPANCIES:

LLNR	AID NAME	DISCREPANCY	•	CHARTBNM	LNM				
00115 30305 31800 17/97	Cape Romain Waccamaw R Coosaw Riv L	iv DBN 14		LT EXT TRUB DBN DEST		11531 101	172-97- N/A 11519	-CHA 173-97	17/97 17/97 -CHA
33590 36730 37355 39480 42335 42405 45805	Mackay Riv Landian Riv N Solution Riv Solution Riv Solution Riv Solution Riv Solution Riv Solution Riv Documents Riv Riv Documents Riv Riv Documents Riv	BN 70 Sec DBN 11 Sec LT 71 LT 29 DBN 46 SBN 4	DBN D	TRUB TRLB TRLB TRUB	11472	11485 11485 11472 11467 11467 184-97		-MAY 7-MAY -MIA 7-MIA -MIA 17/97	17/97 17/97 17/97 17/97 17/97 17/97
53660 54505		mpa Bay DBN 24 mpa Bay DBN 50		TRUB TRUB			265-97- 261-97-		17/97 17/97

FEDERAL DISCREPANCIES CORRECTED:

LLNR	AID NAME	STATUS	CHARI	BINIM	LINIVI					
00205 00250 17/97	Hunting Is LV St Catherines	VB 6HI S Snd LB STC	RELIGI		HING P	11513 ROPERL	134-97- -Y	-CHA 11511	16/97 N/A	
01505 17/97	Winyah Bay L	ower Rng E Fror	t LT	WATC	HING P	ROPERL	_Y	11532	162-97	-CHA
01955 04115	Charleston H	or Ch LBB 20 Cut Rng LB 20			HTED	TATION	11523 11512	170-97 167-97		17/97 17/97
04120	Tybee Knoll C	Cut Rng LB 21		RESE	T ON S	TATION	11512	168-97	-CHA	17/97
04130 05165 17/97		Cut Rng LB 25 Snd LB STC				TATION PROPERL		169-97 11511		17/97
05590 17/97	Brunswick Pt	Cut LB 26		WATC	HING P	ROPERL	_Y	11506	232-97	-MAY
06590	Sherman Cut		DELIC		HTED	11100		222-97		16/97
07230 09430 14/97	Forrester Pt L Miami Main C		RELIGI		HING P	PROPERL	238-97- -Y	11468	17/97 175-97	-MIA
12570 17/97	Boot Key Hbr	DBN 19		WATC	HING P	ROPERL	_Y	11449	N/A	
13620 17/97	Garrison Bigh	t Ch LT 16		WATC	HING P	ROPERL	_Y	11441	N/A	
13750 16/97	Key West NW	/ Ch Ent LBB 1		WATC	HING P	ROPERL	_Y	11441	055-97	-KEY
17675	Charlotte Hbr	Ch B 4	RESET	ON S	TATION	11425	N/A		15/97	

19285 17/97	New Pass Ch DBN 15	WATCHING PROPERL	Υ.	11425 N	N/A
19790	Egmont Ch LWB 13	RELIGHTED	11411	237-97-S	STP 16/97
19805	Egmont Ch LBB 16	RELIGHTED	11411	249-97-S	STP 16/97
19815	Egmont Ch LB 18	RELIGHTED 11411	N/A	1	7/97
27265	Punta Borinquen LT	RELIGHTED	25671	147-97-G	SE 17/97
31570	S Edisto Riv Rng A Front LT	REBUILT/RECOVEREI)	11518 1	65-97-CHA
17/97	_				
34710	Sisters Cr LT 86	WATCHING PROPERLY	11489	N/A	17/97
34715	Sisters Cr LT 88	RELIGHTED 11489	240-97	-MAY 1	7/97
40870	Indian Riv S Sec DBN 189	WATCHING PROPERL	Υ_	11472 2	212-97-MIA
17/97					
42520	Lake Boca Raton LT 65	RELIGHTED	11467	213-97-M	IIA 17/97
45275	Cutter Bank LT 10	WATCHING PROPERLY	11463	196-97-M	IIA 16/97
45565	Tarpon Basin LT 48	WATCHING PROPERLY	11463	057-97-K	EY 17/97
56230	St Joseph Snd DBN 2	WATCHING PROPERL	Υ_	11411 N	N/A
17/97	·				

PRIVATE AID DISCREPANCIES:

LLNR AID NAME DISCREPANCY CHARTBNM LNM

None.

PRIVATE DISCREPANCIES CORRECTED:

LLNR AID NAME STATUS CHARTBNM LNM

41813 *Loxahatchee River B 9 RESET ON STATION 11472 090-97-MIA 09/97

III. TEMPORARY CHANGES-AIDS ESTABLISHED:

LLNR AID NAME STATUS CHARTBNM LNM

1250 Little Riv Inl DBN 15 DISCON/Dredging 11534 159-97-CHA 17-97

TEMPORARY AIDS CORRECTED:

LLNR	AID NAME	STATUS	CHARTBNM	LNM			
			OC/Dredging		072-97-CHA	09-97	
4115	Tybee Knoll Cu	ut Rng LB 20	RELOC/Dredg	ing	11512 057-97	'-CHA	08-97
4120	Tybee Knoll Cu	ut Rng LB 21	RELOC/Dredg	ing	11512 058-97	'-CHA	08-97
17672	Charlotte Hbr (ChB3A REL	OC/Dredging	11425	178-97-STP	13-97	
17695	Charlotte Hbr (Ch LBB 8 REL	OC/Dredging	11425	162-97-STP	12-97	

IV. CHART CORRECTIONS

(Explanation of Format)

Corrective action, affecting charts, is contained in this section. Chart corrections are listed numerically by chart number, beginning with the lowest and progressing through all charts affected. The correction

listed pertains to that chart only. It is up to the mariner to decide which charts are to be corrected. The following example explains the individual elements of a typical correction.

	Chart			Last Local No to Mariners	tice datum	Referen			Current Notice
	number	edition	uale	to manners	uatum	correction	on to ivian	ners	
	1								
11534	26 th ed.	12/14/9	1	Last LNM 41/	92		NAD 83(CG7)	06/93	
(Temp)	Myrtle G	Grove So	ound to	Fear River to C	Casino Cre	eek			
	Add	Boguse	Channe	el Light 1, Fl G	2.5s, 16 f	t, 7M			32248'00"N
79 ² 15'0	0"W	_							
	:	I							
Cor acti	rective		Object action	of corrective	Positio	n			

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (M).

Dates of Latest Editions Announcment

The Dates of Latest Editions, Nautical Charts and Miscellaneous Maps, dated April 1, 1997, published by the National Ocean Service, is available for issue. It may be obtained free from the Distribution Division, N/ACC3, National Ocean Service, 6501 Lafayette Avenue, Riverdale, MD, 20737-1199. This is a quarterly publication listing the most recent editions of nautical charts, miscellaneous maps and publications relating to navigation, weather, etc. with brief descriptions and prices of each.

```
45<sup>th</sup> ed., 10/12/96 LAST LNM 12/97 NAD 83
411
                                                                                                17/97
        Gulf of Mexico
                                                                                                (CGD07)
        DELETE
                          Surface Mooring Buoy from
        28200'00.0"N 084200'00.0"W
    (CGD07)
        RELOCATE
                          Smith ShI Lt from
                 (24<sup>2</sup>43'06.000"N, 81<sup>2</sup>55'17.00"W) to
                                                                                                24<sup>2</sup>43'05.8"N
081255'17 5"W
1113 A 24<sup>th</sup> ed., 11/23/96 LAST LNM 11/97 NAD 83
                                                                                                17/97
        Havana to Tampa Bay - Mineral Lease Chart
        (CGD07)
                          Stock Is App Chan Lt "32" from
        RELOCATE
                 (24<sup>2</sup>28'28.238"N, 81<sup>2</sup>44'32.221"W) to
                                                                                                24228'28.9"N
081244'31.8"W
    Smith ShI Lt from
                 (24<sup>2</sup>43'06.000"N, 81<sup>2</sup>55'17.00"W) to
                                                                                                24243'05.8"N
081255'17.5"W
11006 28<sup>th</sup> ed., 09/09/95 LAST LNM 12/97 NAD 83
                                                                                                17/97
        Gulf Coast - Key West to Mississippi River
        (CGD07)
                          Surface Mooring Buoy from
        DELETE
        28200'00.0"N 084200'00.0"W
    (CGD07)
        RELOCATE
                          Sand Key Lt from
                 (24<sup>2</sup>27'14.774"N, 81<sup>2</sup>52'30.36"W) to
                                                                                                24<sup>2</sup>27'14.7"N
081252'31.3"W
```

Smith ShI Lt from

Sither Still Let Hottl	
(24 ² 43'06.000"N, 81 ² 55'17.00"W) to 081 ² 55'17.5"W	24 ² 43'05.8"N
11013 42 nd ed., 07/13/96 LAST LNM 11/97 NAD 83 Straits of Florida and Approaches (CGD07) DELETE Surface Mooring Buoy from 28²00'00.0"N 084²00'00.0"W (CGD07)	17/97
RELOCATE Sand Key Lt from (24²27'14.774"N, 81²52'30.36"W) to	24 ² 27'14.7"N
081 ² 52'31.3"W	
11420 24 th ed., 11/23/96 LAST LNM 11/97 NAD 83 Havana to Tampa Bay (CGD07)	17/97
RELOCATE Stock Is App Chan Lt "32" from (24°28'28.238"N, 81°44'32.221"W) to	24 ² 28'28.9"N
081 ² 44'31.8"W Sand Key Lt from	24 20 20.0 W
(24 ² 27'14.774"N, 81 ² 52'30.36"W) to	24 ² 27'14.7"N 081 ² 52'31.3"W
Smith ShI Lt from	
(24 ² 43'06.000"N, 81 ² 55'17.00"W) to 081 ² 55'17.5"W	24 ² 43'05.8"N
11425 31 st ed., 10/05/96 LAST LNM 16/97 NAD 83 Charlotte Harbor to Tampa Bay (CGD07)	17/97
RELOCATE Charlotte Hbr Chan Buoy "3A" from (26²40'46.4''N, 82²18'48.3''W) to	26²40'54.2"N
082 ² 18'43.4"W (Previously Temp Relocated 13/97)	
Charlotte Hbr Chan Lighted Bell Buoy "8" from	
(26 ² 41'40.7"N, 82 ² 18'04.8"W) to	26 ² 41'47.3"N 082 ² 17'56.1"W
(Previously Temp Relocated 12/97)	
11426 33 rd ed., 06/01/96 LAST LNM 16/97 NAD 83 Estero Bay to Lemon Bay (CGD07)	17/97
RELOCATE Charlotte Hbr Chan Buoy "3A" from (26 ² 40'46.4"N, 82 ² 18'48.3"W) to 082 ² 18'43.4"W	26 ² 40'54.2"N
(Previously Temp Relocated 13/97)	
Charlotte Hbr Chan Lighted Bell Buoy "8" from	
	26 ² 41'47.3"N 082 ² 17'56.1"W
(Previously Temp Relocated 12/97)	
11427 30 th ed., 11/02/96 LAST LNM 16/97 NAD 83 Fort Myers to Charlotte Harbor & Wiggins Pass (CGD07)	17/97

RELOCATE Charlotte Hbr Chan Buoy "3A" from (26 ² 40'46.4"N, 82 ² 18'48.3"W) to (Side B)	26²40'54.2"N
082 ² 18'43.4"W (Previously Temp Relocated 13/97)	
Charlotte Hbr Chan Lighted Bell Buoy "8" from	
(26 ² 41'40.7"N, 82 ² 18'04.8"W) to (Side B)	26 ² 41'47.3"N 082 ² 17'56.1"W
(Previously Temp Relocated 12/97)	
11428 29 th ed., 06/17/95 LAST LNM 16/97 NAD 83 St Lucie Inlet to Ft Myers & Lake Okeechobee (CGD07) DELETE Visible Wr (S/V from (Side A, Inset 1) 27²13'13.2"N 080²17'04.8"W	17/97
11434 22 nd ed., 03/21/92 LAST LNM 09/97 NAD 83 Sombrero Key to Dry Tortugas (CGD07) RELOCATE Stock Is App Chan Lt "32" from (24 ² 28'28.238"N, 81 ² 44'32.221"W) to	17/97 24²28'28.9"N
081 ² 44'31.8"W Sand Key Lt from	24-20 20.9 N
(24 ² 27'14.774"N, 81 ² 52'30.36"W) to	24 ² 27'14.7"N 081 ² 52'31.3"W
Smith ShI Lt from	
(24 ² 43'06.000"N, 81 ² 55'17.00"W) to 081 ² 55'17.5"W	24 ² 43'05.8"N
11435 12 th ed., 09/30/89 LAST LNM 08/97 WGS 84 Florida Keys (OPAREA) (CGD07) RELOCATE Smith ShI Lt from	17/97
(24 ² 43'06.000"N, 81 ² 55'17.00"W) to 081 ² 55'17.5"W	24 ² 43'05.8"N
11439 23 rd ed., 01/13/96 LAST LNM 08/97 NAD 83 Sand Key to Rebecca Shoal (CGD07) RELOCATE Sand Key Lt from	17/97
(24 ² 27'14.774"N, 81 ² 52'30.36"W) to 081 ² 52'31.3"W Smith ShI Lt from	24²27'14.7"N
(24²43'06.000"N, 81²55'17.00"W) to	24 ² 43'05.8"N
081 ² 55'17.5"W	21 10 0010 11
11441 37 th ed., 10/01/94 LAST LNM 09/97 NAD 83 Key West Harbor and Approaches (CGD07)	17/97
RELOCATE Stock Is App Chan Lt "32" from (24 ² 28'28.238"N, 81 ² 44'32.221"W) to 081 ² 44'31.8"W Sand Key Lt from	24²28'28.9"N
(24 ² 27'14.774"N, 81 ² 52'30.36"W) to	24 ² 27'14.7"N
081 ² 52'31.3"W	

11442 31st ed., 11/16/96 LAST LNM 10/97 NAD 83 17/97 Sombrero Key to Sand Key (CGD07) RELOCATE Stock Is App Chan Lt "32" from (24282828.238"N, 8124432.221"W) to 24228'28.9"N 081244'31.8"W Sand Key Lt from (24²27'14.774"N, 81²52'30.36"W) to 24227'14.7"N 081252'31.3"W 11445 28th ed., 04/16/94 LAST LNM 09/97 NAD 83 17/97 Sugarloaf Key - Key West - Bahia Honda Key (CGD07) RELOCATE Stock Is App Chan Lt "32" from (24²28'28.238"N, 81²44'32.221"W) to (Side B) 24²28'28.9"N 081²44'31.8"W Sand Key Lt from (24²27'14.774"N, 81²52'30.36"W) to (Side B) 24²27'14.7"N 081²52'31.3"W 11451 27th ed., 02/03/96 LAST LNM 14/97 NAD 83 17/97 Miami to Marathon and Florida Bay (CGD07) RELOCATE Old Rhodes Key Daybeacon "21" from (25²21'23.971"N, 80²11'43.437"W) to (Page A) 25²21'23.9"N 080²11'43.7"W Old Rhodes Key Daybeacon "24" from (25²20'7.655"N, 80²12'58.476"W) to (Page A, B, & Inset 3) 25²20'07.6"N 080²12'58.2"W Old Rhodes Key Daybeacon "23" from (25²20'10.521"N, 80²12'34.224"W) to (Page A) 25²20'09.4"N 080²12'33.9"W Old Rhodes Key Lt "22" from (25²20'53.33"N, 80²12'19.979"W) to (Page A, B, & Inset 3) 25²20'53.0"N 080²12'20.3"W Turtle Hbr W Shl Daybeacon "2" from (25²19'22.073"N, 80²12'39.146"W) to (Page A) 25219'02.1"N 080212'38.8"W 11460 34th ed., 11/02/96 LAST LNM 13/97 NAD 83 17/97 Cape Canaveral to Key West (CGD07) RELOCATE Stock Is App Chan Lt "32" from (24282828.238"N, 8124432.221"W) to 24228'28.9"N 081244'31.8"W 11462 22nd ed., 04/13/96 LAST LNM 08/97 NAD 83 17/97 Fowey Rocks to Alligator Reef (CGD07) RELOCATE Old Rhodes Key Daybeacon "21" from (25²21'23.971"N, 80²11'43.437"W) to 2521'23.9"N 080211'43.7"W

Old Rhodes Key Daybeacon "24" from

(25 ² 20'7.655"N, 80 ² 12'58.476"W) to	25 ² 20'07.6"N 080 ² 12'58.2"W
Old Rhodes Key Daybeacon "23" from	
(25 ² 20'10.521"N, 80 ² 12'34.224"W) to	25 ² 20'09.4"N 080 ² 12'33.9"W
Old Rhodes Key Lt "22" from	
(25 ² 20'53.33"N, 80 ² 12'19.979"W) to	25 ² 20'53.0"N 080 ² 12'20.3"W
Turtle Hbr W Shl Daybeacon "2" from	
(25 ² 19'22.073"N, 80 ² 12'39.146"W) to 080 ² 12'38.8"W	25²19'22.1"N
11463 14 th ed., 11/26/94 LAST LNM 14/97 NAD 83 Sands Key to Matecumbe (CGD07) RELOCATE Old Rhodes Key Daybeacon "24" from (25 ² 20'7.655"N, 80 ² 12'58.476"W) to (Side A) 25 ² 20'07.6"N 080 ² 12'58.2"W Old Rhodes Key Daybeacon "23" from	17/97
(25 ² 20'10.521"N, 80 ² 12'34.224"W) to (Side A) 25 ² 20'09.4"N 080 ² 12'33.9"W	
11466 32 nd ed., 11/16/96 LAST LNM 11/97 NAD 83 Jupiter Inlet to Fowey Rocks (CGD07) RELOCATE Pt Everglades Spoil Bank W Daybeacon from	17/97
(26 ² 5'49.313"N, 80 ² 6'11.158"W) to 080 ² 06'11.1"W	26 ² 05'50.8"N
11467 33 rd ed., 12/14/96 LAST LNM 16/97 NAD 83 West Palm Beach to Miami (CGD07) RELOCATE Pt Everglades Spoil Bank W Daybeacon from (26 ² 5'49.313"N, 80 ² 6'11.158"W) to (Side A, Inset 1) 26 ² 05'50.8"N 080 ² 06'11.1"W	17/97
11469 4 th ed., 09/25/93 LAST LNM 41/94 NAD 27 FL Approaches to Port Everglades (CGD07) RELOCATE Pt Everglades Spoil Bank W Daybeacon from	17/97
(26 ² 5'49.313"N, 80 ² 6'11.158"W) to 080 ² 06'11.1"W	26 ² 05'50.8"N
11470 31 st ed., 11/23/96 LAST LNM 10/97 NAD 83 Ft. Lauderdale to Port Everglades (CGD07)	17/97
RELOCATE Pt Everglades Spoil Bank W Daybeacon from (26 ² 5'49.313"N, 80 ² 6'11.158"W) to 080 ² 06'11.1"W	26²05'50.8"N
11472 28 th ed., 08/05/95 LAST LNM 16/97 NAD 83 Palm Shores to West Palm Beach (CGD07)	17/97
RELOCATE Lake Worth S Daybeacon "6" from	

(26²44'35.889"N, 80²2'52.147"W) to (Side B, Inset 3) 26²44'35.8"N 080²02'52.8"W Lake Worth S Daybeacon "4A" from (26²45'2.708"N, 80²2'54.807"W) to (Side B, Inset 2) 26²45'02.3"N 080²02'54.6"W Lake Worth S Daybeacon "3A" from (26²45'19.687"N, 80²2'53.147"W) to (Side B, Inset 2) 26245'19.2"N 080202'53.5"W 11480 33rd ed., 04/06/96 LAST LNM 14/97 NAD 83 17/97 Charleston Light to Cape Canaveral (NOS SILVER SPRING) (CL-1384. 1387/96) ADD fish haven symbol, 2 mm square, blue tint, and label: Obstn Fish Haven *auth min depth 3 1/4 fms) centered at 32225'16.8"N 080211'46.0"W fish havemn symbol, 2 mm square, blue tint, and label: centered in 32220'45.0"N 080204'54.0"W Obstn Fish Haven (auth min 5 fms) (NOS SILVER SPRING) (CL-1384, 1387/96) depth: 9 fms 3221'00.0"N DELETE 080204'55.0"W 11485 30th ed., 06/08/96 LAST LNM 16/97 NAD 83 17/97 Tolomato River to Palm Shores (CGD07) CHANGE St. Augustine Inl LB "2" to - Buoy "2", R nun in (Previously advertised in LNM 27-95) 29254'57.0"N 081215'47.9"W 11488 20th ed., 03/09/96 LAST LNM 14/97 NAD 83 17/97 Amelia Island to St. Augustine (CGD07) St. Augustine Inl LB "2" to - Buoy "2", R nun in **CHANGE** (Previously advertised in LNM 27-95) 29²54'57.0"N 081215'47.9"W 11492 17th ed., 07/18/92 LAST LNM 12/97 NAD 83 17/97 St. Johns River (Jacksonville to Crescent Lake) (CGD07) RELOCATE Upper Palatka Lt "2" from (29²38'17.829"N, 81²37'23.171"W) to (Side B) 29²38'17.8"N 081²37'23.3"W 11495 14th ed., 09/21/96 LAST LNM 12/97 NAD 83 17/97 St. Johns River (Dunns Creek to Lake Dexter) (CGD07) RELOCATE Lake George Daybeacon "13" from (29212'50.72"N, 81234'50.166"W) to 29212'55.3"N 081234'51.2"W Volusia Lt "18" from (29212'5.64"N. 81234'20.76"W) to 29²12'05.6"N 081²34'20.6"W

29²02'17.6"N 081²24'53.7"W

St. Francis Daybeacon "28" from

(29²2'17.942"N, 81²24'55.039"W) to

St. Francis Lt "30" from	
(29 ² 2'7.843"N, 81 ² 24'39.838"W) to	29202'08.6"N 081224'40.2"W
Revolving Bend Cutoff Daybeacon "31" from	
(29 ² 2'.874"N, 81 ² 24'13.463"W) to and	
REMOVE PA	29 ² 02'00.9"N 081 ² 24'11.7"W
Revolving Bend Lt "32" from	
(29 ² 1'58.643"N, 81 ² 24'14.237"W) to	29 ² 01'58.6"N 081 ² 24'12.5"W
Revolving Bend Lt "34" from	
(29 ² 1'46.143"N, 81 ² 24'2.437"W) to	29 ² 01'46.7"N 081 ² 24'00.8"W
Hermitage Pt Lt "35" from	
(29 ² 1'29.944"N, 81 ² 23'37.836"W) to	29 ² 01'32.1"N 081 ² 23'40.3"W
Hermitage Pt Daybeacon "36" from	
(29 ² 1'24.944"N, 81 ² 23'37.836"W) to	29 ² 01'26.0"N 081 ² 23'37.6"W
Hermitage Pt Daybeacon "38" from	
(29 ² 1'14.144"N, 81 ² 23'29.035"W) to	29 ² 01'14.7"N 081 ² 23'28.7"W
Hermitage Pt Lt "39" from	
(29 ² 1'10.544"N, 81 ² 23'21.935"W) to	29 ² 01'09.3"N 081 ² 23'21.5"W
Happy Hill Lt "41" from	
(28 ² 59'53.046"N, 81 ² 22'37.433"W) to	28 ² 59'52.6"N 081 ² 22'38.2"W
Driggers Isl Lt "42" from	
(28 ² 59'37.447"N, 81 ² 22'34.533"W) to	28 ² 59'37.3"N 081 ² 22'32.9"W
Riverside Daybeacon "43" from	
(28 ² 59'37.647"N, 81 ² 22'27.233"W) to	28 ² 59'37.3"N 081 ² 22'27.8"W
Riverside Lt "45" from	
(28 ² 59'37.947"N, 81 ² 22'17.533"W) to	28 ² 59'37.7"N 081 ² 22'15.3"W
Riverside Daybeacon "46" from	
(28 ² 59'34.911"N, 81 ² 22'2.9"W) to	28 ² 59'34.4"N 081 ² 22'00.9"W
Riverside Lt "47" from	
(28 ² 59'37.547"N, 81 ² 21'56.532"W) to	28 ² 59'36.4"N 081 ² 21'55.7"W
Beresford Peninsula Lt "49" from	
(28 ² 59'.448"N, 81 ² 21'15.331"W) to	28 ² 58'59.2"N 081 ² 21'16.2"W

28258'35.9"N 081221'35.1"W

28258'32.6"N 081221'24.3"W

28258'30.8"N 081221'22.8"W

Beresford Peninsula Lt "53" from (2825835.749"N, 8122134.532"W) to

Hontoun Isl Daybeacon "55" from

(2825832.949"N, 8122124.432"W) to

Hontoun Isl Lt "56" from (28258'30.47"N, 81221'23.142"W) to

Hontoun Isl Daybeacon "58" from	
(28258'42.649"N, 81221'4.131"W) to	28258'42.0"N 081221'05.0"W
Hontoun Isl Lt "60" from	
(28258'42.449"N, 81220'59.731"W) to	28 ² 58'42.8"N 081 ² 20'59.7"W
Lake Beresford Daybeacon "61" from	
(28258'44.349"N, 81220'55.831"W) to	28 ² 58'44.9"N 081 ² 20'56.1"W
Hontoun Isl Daybeacon "62" from	
(28258'39.249"N, 81220'55.331"W) to	28 ² 58'40.0"N 081 ² 20'55.5"W
Beresford Cutoff Lt "63" from	
(28258'26.55"N, 81220'46.331"W) to	28 ² 58'25.4"N 081 ² 20'46.8"W
Beresford Cutoff Daybeacon "65" from	
(28258'21.15"N, 81220'49.431"W) to	28258'22.0"N 081220'48.8"W
Hontoun Isl Lt "66" from	
(28257'57.251"N, 81221'4.032"W) to	28 ² 57'57.0"N 081 ² 21'03.0"W
Hontoun Isl Lt "67" from	
(28 ² 57'30.552''N, 81 ² 20'59.932''W) to	28 ² 57'30.0"N 081 ² 20'59.9"W
Starks Cutoff Lt "69" from	
(28 ² 56'55.953''N, 81 ² 20'45.162"'W) to	28 ² 56'55.1"N 081 ² 20'45.5"W
Starks Cutoff Daybeacon "70" from	
(28 ² 56'48.894"N, 81 ² 20'42.698"W) to	28 ² 56'50.7"N 081 ² 20'44.0"W
Blue Spring Lt "71" from	
(28 ² 56'37.054"N, 81 ² 20'31.132"W) to	28 ² 56'36.9"N 081 ² 20'32.1"W
Blue Spring Lt "73" from	
(28 ² 56'20.455"N, 81 ² 20'41.732"W) to	28 ² 56'20.8"N 081 ² 20'41.8"W
Snake Cr Cutoff Daybeacon "75" from	
(28 ² 56'17.255"N, 81 ² 20'48.333"W) to	28 ² 56'17.5"N 081 ² 20'48.1"W
Snake Cr Cutoff Daybeacon "77" from	
(28 ² 55'59.555"N, 81 ² 21'2.733"W) to 081 ² 21'02.5"W	28 ² 55'59.6"N
11507 28 th ed., 08/03/96 LAST LNM 14/97 NAD 83 SC - GA - Beaufort Riv - St. Simons Sound (CGD07) RELOCATE Elba Isl Turn Basin Lt "B" from (32 ² 4'47.755"N, 80 ² 58'51.401"W) to (Side A) 32 ² 04'47.8"N 080 ² 58'51.1"W	17/97
Elba Isl Turning Basin Lt "D" from	
(32 ² 4'40.755"N, 80 ² 59'5.401"W) to (Side A) 080 ² 59'05.3"W	32²04'36.1"N
Hampton River Daybeacon "11" from	

(31 ² 14'12.6"N, 81 ² 19'24.6"W) to (Side B) 081 ² 19'24.6"W	31²14'12.7"N
11508 19 th ed., 03/06/93 LAST LNM 14/97 NAD 83	17/97
Altamaha Sound (CGD07) RELOCATE Hampton River Daybeacon "11" from (31²14'12.6"N, 81²19'24.6"W) to	31 ² 14'12.7"N
081 ² 19'24.6"W	2
11509 25 th ed., 08/17/96 LAST LNM 14/97 NAD 83 Tybee Island to Doboy Sound (CGD07)	17/97
RELOCATE Bloody Pt Rge LB "11" from (32 ² 1'8.2"N, 80 ² 48'31.9"W) to 080 ² 48'30.6"W	32 ² 01'09.1"N
(Previously Temp Relocated 09/97)	
11512 54 th ed., 09/21/96 LAST LNM 14/97 NAD 83 Savannah River and Wassaw Sound (CGD07) RELOCATE Elba Isl Turn Basin Lt "B" from	17/97
(32 ² 4'47.755"N, 80 ² 58'51.401"W) to 080 ² 58'51.1"W	32 ² 04'47.8"N
Elba Isl Turning Basin Lt "D" from	4100 4111 000350105 011114
,	1'36.1"N 080²59'05.3"W
Bloody Pt Rge LB "11" from	1200 4"NL000240200 0"NA
,	1'09.1"N 080²48'30.6"W
(Previously Temp Relocated 09/97)	
Tybee Knoll Cut Rge LB "20" from	0'46 0"N 000254'06 4"N
	2'16.9"N 080²51'26.4"W
(Previously Temp Relocated 08/97)	
Tybee Knoll Cut Rge LB "21" from	2'0E 6"N 0002E2'22 4"N
	2'05.6"N 080252'23.4"W
(Previously Temp Relocated 08/97) 11513 21 st ed., 06/04/94 LAST LNM 11/97 NAD 83 St. Helena Sound to Savannah River (CGD07)	17/97
RELOCATE Bloody Pt Rge LB "11" from (32 ² 1'8.2"N, 80 ² 48'31.9"W) to 080 ² 48'30.6"W	32 ² 01'09.1"N
(Previously Temp Relocated 09/97)	
11517 15 th ed., 12/24/94 LAST LNM 12/97 NAD 83 St. Helena Sound (CGD07)	17/97
RELOCATE S Edisto River Rge A Front Lt from (32 ² 35'16.833"N, 80 ² 23'58.297"W) to 080 ² 23'58.9"W	32²35'15.9"N
11518 29 th ed., 05/11/96 LAST LNM 16/97 NAD 83	17/97

Casino Creek to Beaufort River

(CGD07)

RELOCATE S Edisto River Rge A Front Lt from

(32²35'16.833"N, 80²23'58.297"W) to (Side B)

32235'15.9"N 080223'58.9"W

11521 22nd ed., 01/20/96 LAST LNM 16/97 NAD 83

17/97

Charleston Harbor and Approaches

(NOS SILVER SPRING) (CL-

1384/96)

ADD black dotted lines, blue tint, and label: Obstn Fish

Haven (auth min depth 20 ft) joining 32²25'31.8"N

080212'03.0"W

to 32²25'01.8"N 080²12'03.0"W

to 32225'01.8"N 080211'30.6"W

to 32225'31.8"N 080211'30.6"W

(NOS SILVER SPRING) (CL-1384/96)

DELETE depth: 47 feet at 32²25'18.0"N

080211'44.0"W

11534 28th ed., 06/11/94 LAST LNM 16/97 NAD 83

17/97

(TEMP) Myrtle Grove Sound to Fear River to Casino Creek

(CGD07)

DELETE Little River Inl Daybeacon "15" from (Side A)

33251'36.8"N 078233'43.9"W

25673 14th ed., 11/10/90 LAST LNM 11/97 NAD 83

17/97

Bahia de Mayaguez

(CGD07)

CHANGE Bahia de Mayaguez Rge Front Lt ht to 33 ft in

18213'08.6"N 067209'44.3"W

V. NEW ADVANCE NOTICE

None.

VI. NEW PROPOSED CHANGES

None.

VII. NEW GENERAL INFORMATION

A. NEW BRIDGE INFORMATION

SOUTH CAROLINA-ASHLEY RIVER: Special Bridge Notice.

The Coast Guard has received a request from the South Carolina Department of Transportation for authorization to remove draw tender service from the two US Highway 17 Bridges across the Ashley River, mile 2.4 from 9:00 p.m. until 5:00 a.m. daily. This request is being made because of the low number of requests for openings at these bridges during evening hours.

If authorized, this proposal would allow both US Highway 17 Bridges across the Ashley River, mile 2.4, not to open for vessel traffic from 9:00 p.m. to 5:00 a.m. daily. During these periods the draw would be opened on signal if at least 24 hours advanced notice is given.

SOUTH CAROLINA-ASHLEY RIVER: Special Bridge Notice. (Cont.)

The Coast Guard is seeking comments on this proposed closure period and the effect it would have on navigation. Comments should be sent to the address on the cover of this notice and should be mailed to arrive no later than May 29, 1997. If you're unable to respond in writing you can comment by calling Gary D. Pruitt at (305) 536-7331.

Chart: 11518 CG File: 3/119

SOUTH CAROLINA-STONO RIVER: Special Bridge Notice.

The Coast Guard has received a request from the South Carolina Department of Transportation for authorization to remove draw tender service from the Stono River Swingbridge (AKA Maybank Highway) across the Stono River, mile 11 from 10:00 p.m. until 5:00 a.m. daily. This request is being made because of the low number of requests for openings at this bridge during evening hours.

If authorized, this proposal would allow the Stono River Swingbridge across the Stono River, mile 11, not to open for vessel traffic from 10:00 p.m. to 5:00 a.m. daily. During these periods the draw would be opened on signal if at least 24 hours advanced notice is given.

The Coast Guard is seeking comments on this proposed closure period and the effect it would have on navigation. Comments should be sent to the address on the cover of this notice and should be mailed to arrive no later than May 29, 1997. If you're unable to respond in writing you can comment by calling Gary D. Pruitt at (305) 536-7331.

Chart: 11518 CG File: 96

FLORIDA-ST. JOHNS RIVER-FULLER WARREN: Bridge Construction.

The Fuller Warren Bridge is under construction. Construction equipment will be working adjacent to the channel on a daily basis from 9:30 p.m. to 3:30 a.m. until May 05, 1997. Mariner can contact the tug BB on VHF-FM channel 11 for maneuvering information.

Ref: BNM 245-97-MAY Chart; 11491

FLORIDA-MANATEE RIVER: Bridge Discrepancy Correction.

Navigation lights reported extinguished on the fixed highway bridges at mile 4.3 and 4.8 at Brandenton have been relighted.

Chart: CG File:

FLORIDA-TAMPA BAY TO ANCLOTE ANCHORAGE-ANCLOTE RIVER: Bridge Construction.

Interbay Marine Construction is repairing the fender system of the Alternate 19 Bridge across Anclote River, mile 3.1 at Tarpon Springs through May 21, 1997. The tug MISS GINA can be contacted on VHF-FM channels 9 or 16 for passing information.

Chart: 11412 CG File: 2133

FLORIDA-INTRACOASTAL WATERWAY-WEST PALM BEACH-MIAMI-BISCAYNE BAY: Special Drawbridge Notice.

The Coast Guard has authorized the Old Dodge Island (Port of Miami) Drawbridge from the mainland to the Port of Miami across the Intercoastal Waterway, mile 1089.4, Miami, Dade County, Florida, to

remain closed to navigation from 6:45 a.m. to 8:15 a.m. on Thursday, May 01, 1997, to accommodate the Office Depot Corporate Run Event.

Chart: 11467 CG File: 3051

B. MISCELLANEOUS INFORMATION

SOUTH CAROLINA-SEACOAST-NORTH MYRTLE BEACH TO GEORGETOWN: Fishing Tournament.

The Annual March of Dimes Offshore Flounder Fishing Tournament will be held on may 17, 1997, from 6:30 .am. to 4:00 p.m. There will be approximately 200 vessels participating.

Chart: 11535

SOUTH CAROLINA-CHARLESTON HARBOR: Regatta.

The annual Armed Forces Regatta will be held on May 17 and 18, 1997, from 11:00 a.m. to 5:00 p.m. on Middle Ground, south of Shutes Folly Island, Charleston. There will be approximately 30 sailboats participating.

Chart: 11524

SOUTH CAROLINA-STONO AND NORTH EDISTO RIVERS-FOLLY RIVER: Shoaling.

Severe shoaling exists between Folly River Light 9 (LLNR 3130) and - Daybeacon 10 (LLNR 3135). The dredge CLAIRADON is currently dredging this area and is expected to be completed on April 30, 1997. The dredge can be contacted on VHF-FM channel 13 for passing information.

Ref: BNM 163-97-CHA Chart: 11522

SOUTH CAROLINA-PORT ROYAL SOUND-BROAD RIVER: U.S. Marine Corps Operations.

On Saturday, May 03 and Sunday, May 04, 1997, Marine Corps Recruit Depot Parris Island, South Carolina, will be conducting live fire training, requiring the access to Ribbons Creek and Archers Creek to be shut down between the hours of 6:00 a.m. and 5:00 p.m.

Ref: BNM 164-97-CHA Chart: 11516

GEORGIA-CUMBERLAND SOUND-FERNANDINA HARBOR-KINGS BAY: Dredging Operations.

The Captain of the Port Jacksonville, advises mariners that dredging operations are being conducted in Kings Bay between Kings Bay Lighted Buoy 49 (LLNR 6295/34115) and - LIGHT 50 (LLNR 6320/34110), until May 29, 1997. The dredge can be contacted on VHF-FM channels 13 or 16 for passing information.

Ref: BNM 236-97-MAY and 441-97-D7 Chart: 11503

FLORIDA-INTRACOASTAL WATERWAY-ST. LUCIE INLET TO FORT MYERS AND LAKE OKEECHOBEE-OKEECHOBEE WATERWAY: Low Water Level.

Due to the low level of Lake Okeechobee, actual channel depths are less than advertised. Many sections of Lake Okeechobee (Route 2) have only five feet of water available. All larger vessels are requested to transit via Lake Okeechobee (Route 1). This condition is expected to last until July.

Ref: BNM 215-97-MIA Chart: 11428

VIII. LIGHT LIST CORRECTIONS

(1) No.	(2) (3) Name and Location Remarks	(4) Position	(5) Charac	(6) teristic	(7) Ht	(8) Rng	Structure
290	St. Simons Lighted RACON: B ().	31 03.2 Mo (A)	W		6	Red an	d white stripes with
5405 •	Whistle Buoy STS (17-97)	81 15.1			red spl	herical to	opmark.
775	Sand Key Light 24 27.2 FI (2) W 15s 40 13 81 52.5 0.1s fl 2.4s ec tower. 0.1s fl 12.4s ec			NR on square skeleton			
•	(17-97)						
5405	St. Simons Lighted RACON: B ().	31 03.2 Mo (A)	W		6	Red an	d white stripes with
290	Whistle Buoy STS (17-97)	81 15.1			red spl	herical to	opmark.

Bahia de Mayaguez

28790 - RANGE FRONT LIGHT 18 13.1 Q G 33 KRW on square tower. Visible 22 each side of 67 09.7 rangeline.

• (17-97)

31575 - RANGE A REAR LIGHT Iso R 6s 24 KRW on dolphin.
Visible 4² each side of
109 yards, 206.2² from rangeline.
front light.

• (17-97)

IX. ADDITIONAL ENCLOSURES

Enclosure (1) Report of Channel Conditions for Manatee Harbor, Mantee County, Florida.

Enclosure (2) Change 04A to U.S. Coast Pilot 4, Atlantic Coast: Cape Henry to Key West, 1996 (31 st Edition).

Enclosure (3) Change 12 to U.S. Coast Pilot 5, Atlantic Coast: Gulf of Mexico, Puerto Rico, and Virgin Islands 1996 (26th Edition).

April 22, 1997

John W. Lockwood
Rear Admiral, U.S. Coast Guard
Commander, Seventh Coast Guard District 2
Page # of 09
LNM 17-97
Seventh Coast Guard District